



Comparison of 1987 and 2011  
Photographs of Watts Towers Sculptures

Interior North Wall

April 25, 2012




Interior North Wall  
Post 1  
1987

















Interior North Wall  
 Post 1  
 2011



2011 Analysis/Comparison of Site in  
 Relation to 1987 Rand Photos

LEGEND

					
Mortar Reattachment	New Mortar Application	Missing Ornament	Uncovered Ornament	Treatment Prior to 1987	New Ornament Impression
					
Added/Rearranged Ornament	Crack Fill	Altered Shape or Contour	New Damage	Lost Ornament Impression	Removed Treatment Prior to 1987

NOTE: Dashed line indicates uncertainty/need of verification

Interior North Wall  
Post 2  
1987

















Interior North Wall  
Post 2  
2011



2011 Analysis/Comparison of Site in  
Relation to 1987 Rand Photos


LEGEND

					
Mortar Reattachment	New Mortar Application	Missing Ornament	Uncovered Ornament	Treatment Prior to 1987	New Ornament Impression
					
Added/Rearranged Ornament	Crack Fill	Altered Shape or Contour	New Damage	Lost Ornament Impression	Removed Treatment Prior to 1987


NOTE: Dashed line indicates uncertainty/need of verification



Interior North Wall  
Panel 4 Bottom  
1987















Interior North Wall  
 Panel 4 Bottom  
 2011



2011 Analysis/Comparison of Site in  
 Relation to 1987 Rand Photos


LEGEND

					
Mortar Reattachment	New Mortar Application	Missing Ornament	Uncovered Ornament	Treatment Prior to 1987	New Ornament Impression
					
Added/Rearranged Ornament	Crack Fill	Altered Shape or Contour	New Damage	Lost Ornament Impression	Removed Treatment Prior to 1987

NOTE: Dashed line indicates uncertainty/need of verification



Interior North Wall  
Panel 4 Top  
1987

















Interior North Wall  
 Panel 4 Top  
 2011



2011 Analysis/Comparison of Site in  
 Relation to 1987 Rand Photos



LEGEND

					
Mortar Reattachment	New Mortar Application	Missing Ornament	Uncovered Ornament	Treatment Prior to 1987	New Ornament Impression
					
Added/Rearranged Ornament	Crack Fill	Altered Shape or Contour	New Damage	Lost Ornament Impression	Removed Treatment Prior to 1987

NOTE: Dashed line indicates uncertainty/need of verification



Interior North Wall  
Panel 4 Top Left  
1987















Interior North Wall  
 Panel 4 Top Left  
 2011



2011 Analysis/Comparison of Site in  
 Relation to 1987 Rand Photos


LEGEND

					
Mortar Reattachment	New Mortar Application	Missing Ornament	Uncovered Ornament	Treatment Prior to 1987	New Ornament Impression
					
Added/Rearranged Ornament	Crack Fill	Altered Shape or Contour	New Damage	Lost Ornament Impression	Removed Treatment Prior to 1987


NOTE: Dashed line indicates uncertainty/need of verification



Interior North Wall  
Panel 5 Bottom  
1987















Interior North Wall  
 Panel 5 Bottom  
 2011



2011 Analysis/Comparison of Site in  
 Relation to 1987 Rand Photos


LEGEND

					
Mortar Reattachment	New Mortar Application	Missing Ornament	Uncovered Ornament	Treatment Prior to 1987	New Ornament Impression
					
Added/Rearranged Ornament	Crack Fill	Altered Shape or Contour	New Damage	Lost Ornament Impression	Removed Treatment Prior to 1987

NOTE: Dashed line indicates uncertainty/need of verification



Interior North Wall  
Panel 5 Left  
1987

















Interior North Wall  
 Panel 5 Left  
 2011



2011 Analysis/Comparison of Site in  
 Relation to 1987 Rand Photos


LEGEND

					
Mortar Reattachment	New Mortar Application	Missing Ornament	Uncovered Ornament	Treatment Prior to 1987	New Ornament Impression
					
Added/Rearranged Ornament	Crack Fill	Altered Shape or Contour	New Damage	Lost Ornament Impression	Removed Treatment Prior to 1987


NOTE: Dashed line indicates uncertainty/need of verification



Interior North Wall  
Panel 5 Top Right  
1987















Interior North Wall  
 Panel 5 Top Right  
 2011



2011 Analysis/Comparison of Site in  
 Relation to 1987 Rand Photos



LEGEND

					
Mortar Reattachment	New Mortar Application	Missing Ornament	Uncovered Ornament	Treatment Prior to 1987	New Ornament Impression
					
Added/Rearranged Ornament	Crack Fill	Altered Shape or Contour	New Damage	Lost Ornament Impression	Removed Treatment Prior to 1987

NOTE: Dashed line indicates uncertainty/need of verification



Interior North Wall  
Panel 6  
1987

















Interior North Wall  
 Panel 6  
 2011



2011 Analysis/Comparison of Site in  
 Relation to 1987 Rand Photos



LEGEND

					
Mortar Reattachment	New Mortar Application	Missing Ornament	Uncovered Ornament	Treatment Prior to 1987	New Ornament Impression
					
Added/Rearranged Ornament	Crack Fill	Altered Shape or Contour	New Damage	Lost Ornament Impression	Removed Treatment Prior to 1987

NOTE: Dashed line indicates uncertainty/need of verification




Interior North Wall  
Panel 7  
1987

















Interior North Wall  
 Panel 7  
 2011



2011 Analysis/Comparison of Site in  
 Relation to 1987 Rand Photos



LEGEND

					
Mortar Reattachment	New Mortar Application	Missing Ornament	Uncovered Ornament	Treatment Prior to 1987	New Ornament Impression
					
Added/Rearranged Ornament	Crack Fill	Altered Shape or Contour	New Damage	Lost Ornament Impression	Removed Treatment Prior to 1987

NOTE: Dashed line indicates uncertainty/need of verification



Interior North Wall  
Panel 8  
1987

















Interior North Wall  
 Panel 8  
 2011



2011 Analysis/Comparison of Site in  
 Relation to 1987 Rand Photos




LEGEND

					
Mortar Reattachment	New Mortar Application	Missing Ornament	Uncovered Ornament	Treatment Prior to 1987	New Ornament Impression
					
Added/Rearranged Ornament	Crack Fill	Altered Shape or Contour	New Damage	Lost Ornament Impression	Removed Treatment Prior to 1987

NOTE: Dashed line indicates uncertainty/need of verification




Interior North Wall  
Panel 9  
1987

















Interior North Wall  
 Panel 9  
 2011



2011 Analysis/Comparison of Site in  
 Relation to 1987 Rand Photos


LEGEND

					
Mortar Reattachment	New Mortar Application	Missing Ornament	Uncovered Ornament	Treatment Prior to 1987	New Ornament Impression
					
Added/Rearranged Ornament	Crack Fill	Altered Shape or Contour	New Damage	Lost Ornament Impression	Removed Treatment Prior to 1987

NOTE: Dashed line indicates uncertainty/need of verification



Interior North Wall  
Panel 9 Looking Northeast  
1987















Interior North Wall  
 Panel 9 Looking Northeast  
 2011



2011 Analysis/Comparison of Site in  
 Relation to 1987 Rand Photos


**LEGEND**

 <b>Mortar Reattachment</b>	 <b>New Mortar Application</b>	 <b>Missing Ornament</b>	 <b>Uncovered Ornament</b>	 <b>Treatment Prior to 1987</b>	 <b>TRANSPARENT</b> <b>New Ornament Impression</b>
 <b>Added/Rearranged Ornament</b>	 <b>Crack Fill</b>	 <b>Altered Shape or Contour</b>	 <b>New Damage</b>	 <b>TRANSPARENT</b> <b>Lost Ornament Impression</b>	 <b>TRANSPARENT</b> <b>Removed Treatment Prior to 1987</b>


NOTE: Dashed line indicates uncertainty/need of verification



Interior North Wall  
Fountain Looking North  
1987















Interior North Wall  
 Fountain Looking North  
 2011



2011 Analysis/Comparison of Site in  
 Relation to 1987 Rand Photos


LEGEND

					
Mortar Reattachment	New Mortar Application	Missing Ornament	Uncovered Ornament	Treatment Prior to 1987	TRANSPARENT
					
Added/Rearranged Ornament	Crack Fill	Altered Shape or Contour	New Damage	Lost Ornament Impression	Removed Treatment Prior to 1987

NOTE: Dashed line indicates uncertainty/need of verification



Interior North Wall  
Fountain Looking East  
1987

















Interior North Wall  
Fountain Looking East  
2011



2011 Analysis/Comparison of Site in  
Relation to 1987 Rand Photos


LEGEND

					
Mortar Reattachment	New Mortar Application	Missing Ornament	Uncovered Ornament	Treatment Prior to 1987	New Ornament Impression
					
Added/Rearranged Ornament	Crack Fill	Altered Shape or Contour	New Damage	Lost Ornament Impression	Removed Treatment Prior to 1987

NOTE: Dashed line indicates uncertainty/need of verification



Interior North Wall  
Panel 10  
1987

















Interior North Wall  
 Panel 10  
 2011



2011 Analysis/Comparison of Site in  
 Relation to 1987 Rand Photos

LEGEND

					
Mortar Reattachment	New Mortar Application	Missing Ornament	Uncovered Ornament	Treatment Prior to 1987	TRANSPARENT New Ornament Impression
					
Added/Rearranged Ornament	Crack Fill	Altered Shape or Contour	New Damage	TRANSPARENT Lost Ornament Impression	TRANSPARENT Removed Treatment Prior to 1987

NOTE: Dashed line indicates uncertainty/need of verification



Interior North Wall  
Panel 11  
1987

















Interior North Wall  
 Panel 11  
 2011



2011 Analysis/Comparison of Site in  
 Relation to 1987 Rand Photos


LEGEND

					
Mortar Reattachment	New Mortar Application	Missing Ornament	Uncovered Ornament	Treatment Prior to 1987	New Ornament Impression
					
Added/Rearranged Ornament	Crack Fill	Altered Shape or Contour	New Damage	Lost Ornament Impression	Removed Treatment Prior to 1987

NOTE: Dashed line indicates uncertainty/need of verification




Interior North Wall  
Panel 12  
1987

















Interior North Wall  
 Panel 12  
 2011



2011 Analysis/Comparison of Site in  
 Relation to 1987 Rand Photos


LEGEND

					
Mortar Reattachment	New Mortar Application	Missing Ornament	Uncovered Ornament	Treatment Prior to 1987	New Ornament Impression
					
Added/Rearranged Ornament	Crack Fill	Altered Shape or Contour	New Damage	Lost Ornament Impression	Removed Treatment Prior to 1987

NOTE: Dashed line indicates uncertainty/need of verification



Interior North Wall  
Panel 13  
1987

















Interior North Wall  
 Panel 13  
 2011



2011 Analysis/Comparison of Site in  
 Relation to 1987 Rand Photos



LEGEND

					
Mortar Reattachment	New Mortar Application	Missing Ornament	Uncovered Ornament	Treatment Prior to 1987	New Ornament Impression
					
Added/Rearranged Ornament	Crack Fill	Altered Shape or Contour	New Damage	Lost Ornament Impression	Removed Treatment Prior to 1987

NOTE: Dashed line indicates uncertainty/need of verification



Interior North Wall  
Panel 14  
1987

















Interior North Wall  
 Panel 14  
 2011



2011 Analysis/Comparison of Site in  
 Relation to 1987 Rand Photos


LEGEND

					
Mortar Reattachment	New Mortar Application	Missing Ornament	Uncovered Ornament	Treatment Prior to 1987	New Ornament Impression
					
Added/Rearranged Ornament	Crack Fill	Altered Shape or Contour	New Damage	Lost Ornament Impression	Removed Treatment Prior to 1987

NOTE: Dashed line indicates uncertainty/need of verification




Interior North Wall  
Post 14  
1987

















Interior North Wall  
 Post 14  
 2011



2011 Analysis/Comparison of Site in  
 Relation to 1987 Rand Photos




LEGEND

					
Mortar Reattachment	New Mortar Application	Missing Ornament	Uncovered Ornament	Treatment Prior to 1987	New Ornament Impression
					
Added/Rearranged Ornament	Crack Fill	Altered Shape or Contour	New Damage	Lost Ornament Impression	Removed Treatment Prior to 1987

NOTE: Dashed line indicates uncertainty/need of verification




Interior North Wall  
Chimney  
1987

















Interior North Wall  
Chimney  
2011



2011 Analysis/Comparison of Site in  
Relation to 1987 Rand Photos

LEGEND

					
Mortar Reattachment	New Mortar Application	Missing Ornament	Uncovered Ornament	Treatment Prior to 1987	New Ornament Impression
					
Added/Rearranged Ornament	Crack Fill	Altered Shape or Contour	New Damage	Lost Ornament Impression	Removed Treatment Prior to 1987

NOTE: Dashed line indicates uncertainty/need of verification



Interior North Wall  
Chimney Top  
1987

















Interior North Wall  
Chimney Top  
2011



2011 Analysis/Comparison of Site in  
Relation to 1987 Rand Photos




LEGEND

					
Mortar Reattachment	New Mortar Application	Missing Ornament	Uncovered Ornament	Treatment Prior to 1987	New Ornament Impression
					
Added/Rearranged Ornament	Crack Fill	Altered Shape or Contour	New Damage	Lost Ornament Impression	Removed Treatment Prior to 1987


NOTE: Dashed line indicates uncertainty/need of verification



Interior North Wall  
Panel 16  
1987















Interior North Wall  
 Panel 16  
 2011



2011 Analysis/Comparison of Site in  
 Relation to 1987 Rand Photos

LEGEND

					
Mortar Reattachment	New Mortar Application	Missing Ornament	Uncovered Ornament	Treatment Prior to 1987	New Ornament Impression
					
Added/Rearranged Ornament	Crack Fill	Altered Shape or Contour	New Damage	Lost Ornament Impression	Removed Treatment Prior to 1987

NOTE: Dashed line indicates uncertainty/need of verification



Interior North Wall  
Post 16  
1987















Interior North Wall  
 Post 16  
 2011



2011 Analysis/Comparison of Site in  
 Relation to 1987 Rand Photos

LEGEND

					
Mortar Reattachment	New Mortar Application	Missing Ornament	Uncovered Ornament	Treatment Prior to 1987	New Ornament Impression
					
Added/Rearranged Ornament	Crack Fill	Altered Shape or Contour	New Damage	Lost Ornament Impression	Removed Treatment Prior to 1987

NOTE: Dashed line indicates uncertainty/need of verification