


Comparison of 1987 and 2011  
Photographs of Watts Towers Sculptures

Interior South Wall


April 18, 2012



Interior South Wall  
Panel 1,2 and 3  
1987















Interior South Wall  
 Panel 1, 2 and 3  
 2011




2011 Analysis/Comparison of Site in  
 Relation to 1987 Rand Photos

LEGEND

					
Mortar Reattachment	New Mortar Application	Missing Ornament	Uncovered Ornament	Treatment Prior to 1987	New Ornament Impression
					
Added/Rearranged Ornament	Crack Fill	Altered Shape or Contour	New Damage	Lost Ornament Impression	Removed Treatment Prior to 1987

NOTE: Dashed line indicates uncertainty/need of verification

Interior South Wall  
Panel 4  
1987















Interior South Wall  
 Panel 4  
 2011




2011 Analysis/Comparison of Site in  
 Relation to 1987 Rand Photos

LEGEND


					
Mortar Reattachment	New Mortar Application	Missing Ornament	Uncovered Ornament	Treatment Prior to 1987	New Ornament Impression
					
Added/Rearranged Ornament	Crack Fill	Altered Shape or Contour	New Damage	Lost Ornament Impression	Removed Treatment Prior to 1987

NOTE: Dashed line indicates uncertainty/need of verification

Interior South Wall  
Panel 5 Bottom  
1987















Interior South Wall  
 Panel 5 Bottom  
 2011



2011 Analysis/Comparison of Site in  
 Relation to 1987 Rand Photos



LEGEND

					
Mortar Reattachment	New Mortar Application	Missing Ornament	Uncovered Ornament	Treatment Prior to 1987	New Ornament Impression
					
Added/Rearranged Ornament	Crack Fill	Altered Shape or Contour	New Damage	Lost Ornament Impression	Removed Treatment Prior to 1987

NOTE: Dashed line indicates uncertainty/need of verification



Interior South Wall  
Panel 5 Top  
1987















Interior South Wall  
 Panel 5 Top  
 2011




2011 Analysis/Comparison of Site in  
 Relation to 1987 Rand Photos

LEGEND


					
Mortar Reattachment	New Mortar Application	Missing Ornament	Uncovered Ornament	Treatment Prior to 1987	TRANSPARENT New Ornament Impression
					
Added/Rearranged Ornament	Crack Fill	Altered Shape or Contour	New Damage	TRANSPARENT Lost Ornament Impression	TRANSPARENT Removed Treatment Prior to 1987

NOTE: Dashed line indicates uncertainty/need of verification

Interior South Wall  
Panel 6 Bottom  
1987















Interior South Wall  
 Panel 6 Bottom  
 2011




2011 Analysis/Comparison of Site in  
 Relation to 1987 Rand Photos

LEGEND


					
Mortar Reattachment	New Mortar Application	Missing Ornament	Uncovered Ornament	Treatment Prior to 1987	New Ornament Impression
					
Added/Rearranged Ornament	Crack Fill	Altered Shape or Contour	New Damage	Lost Ornament Impression	Removed Treatment Prior to 1987

NOTE: Dashed line indicates uncertainty/need of verification

Interior South Wall  
Panel 6 Bottom  
1987















Interior South Wall  
 Panel 6 Top  
 2011



2011 Analysis/Comparison of Site in  
 Relation to 1987 Rand Photos

LEGEND

					
Mortar Reattachment	New Mortar Application	Missing Ornament	Uncovered Ornament	Treatment Prior to 1987	New Ornament Impression
					
Added/Rearranged Ornament	Crack Fill	Altered Shape or Contour	New Damage	Lost Ornament Impression	Removed Treatment Prior to 1987

NOTE: Dashed line indicates uncertainty/need of verification

Interior South Wall  
Panel 7  
1987















Interior South Wall  
 Panel 7  
 2011



2011 Analysis/Comparison of Site in  
 Relation to 1987 Rand Photos


LEGEND

					
Mortar Reattachment	New Mortar Application	Missing Ornament	Uncovered Ornament	Treatment Prior to 1987	New Ornament Impression
					
Added/Rearranged Ornament	Crack Fill	Altered Shape or Contour	New Damage	Lost Ornament Impression	Removed Treatment Prior to 1987


NOTE: Dashed line indicates uncertainty/need of verification



Interior South Wall  
Panel 8  
1987















Interior South Wall  
 Panel 8  
 2011




2011 Analysis/Comparison of Site in  
 Relation to 1987 Rand Photos

LEGEND


					
Mortar Reattachment	New Mortar Application	Missing Ornament	Uncovered Ornament	Treatment Prior to 1987	New Ornament Impression
					
Added/Rearranged Ornament	Crack Fill	Altered Shape or Contour	New Damage	Lost Ornament Impression	Removed Treatment Prior to 1987

NOTE: Dashed line indicates uncertainty/need of verification

Interior South Wall  
Panel 9  
1987















Interior South Wall  
 Panel 9  
 2011



2011 Analysis/Comparison of Site in  
 Relation to 1987 Rand Photos

LEGEND

					
Mortar Reattachment	New Mortar Application	Missing Ornament	Uncovered Ornament	Treatment Prior to 1987	New Ornament Impression
					
Added/Rearranged Ornament	Crack Fill	Altered Shape or Contour	New Damage	Lost Ornament Impression	Removed Treatment Prior to 1987

NOTE: Dashed line indicates uncertainty/need of verification

Interior South Wall  
Panel 10 and 11  
1987















Interior South Wall  
 Panel 10 and 11  
 2011



Looks like completely different surface

2011 Analysis/Comparison of Site in  
 Relation to 1987 Rand Photos

LEGEND

					
Mortar Reattachment	New Mortar Application	Missing Ornament	Uncovered Ornament	Treatment Prior to 1987	New Ornament Impression
					
Added/Rearranged Ornament	Crack Fill	Altered Shape or Contour	New Damage	Lost Ornament Impression	Removed Treatment Prior to 1987

NOTE: Dashed line indicates uncertainty/need of verification

Interior South Wall  
Panel 11 and 12  
1987















Interior South Wall  
 Panel 11 and 12  
 2011



2011 Analysis/Comparison of Site in  
 Relation to 1987 Rand Photos

LEGEND

					
Mortar Reattachment	New Mortar Application	Missing Ornament	Uncovered Ornament	Treatment Prior to 1987	New Ornament Impression
					
Added/Rearranged Ornament	Crack Fill	Altered Shape or Contour	New Damage	Lost Ornament Impression	Removed Treatment Prior to 1987

NOTE: Dashed line indicates uncertainty/need of verification



Interior South Wall  
Panel 13  
1987















Interior South Wall  
 Panel 13  
 2011




2011 Analysis/Comparison of Site in  
 Relation to 1987 Rand Photos

LEGEND

					
Mortar Reattachment	New Mortar Application	Missing Ornament	Uncovered Ornament	Treatment Prior to 1987	New Ornament Impression
					
Added/Rearranged Ornament	Crack Fill	Altered Shape or Contour	New Damage	Lost Ornament Impression	Removed Treatment Prior to 1987

NOTE: Dashed line indicates uncertainty/need of verification

Interior South Wall  
East Gate and Post 14  
1987















Interior South Wall  
 East Gate and Post 14  
 2011




2011 Analysis/Comparison of Site in  
 Relation to 1987 Rand Photos

LEGEND

					
Mortar Reattachment	New Mortar Application	Missing Ornament	Uncovered Ornament	Treatment Prior to 1987	TRANSPARENT New Ornament Impression
					
Added/Rearranged Ornament	Crack Fill	Altered Shape or Contour	New Damage	TRANSPARENT Lost Ornament Impression	TRANSPARENT Removed Treatment Prior to 1987

NOTE: Dashed line indicates uncertainty/need of verification

Interior South Wall  
Pinnacles Looking West  
1987















Interior South Wall  
Pinnacles Looking West  
2011





2011 Analysis/Comparison of Site in  
Relation to 1987 Rand Photos

LEGEND


					
Mortar Reattachment	New Mortar Application	Missing Ornament	Uncovered Ornament	Treatment Prior to 1987	TRANSPARENT New Ornament Impression
					
Added/Rearranged Ornament	Crack Fill	Altered Shape or Contour	New Damage	TRANSPARENT Lost Ornament Impression	TRANSPARENT Removed Treatment Prior to 1987

NOTE: Dashed line indicates uncertainty/need of verification

Interior South Wall  
Pinnacles Looking South  
1987















Interior South Wall  
Pinnacles Looking South  
2011



2011 Analysis/Comparison of Site in  
Relation to 1987 Rand Photos


LEGEND

					
Mortar Reattachment	New Mortar Application	Missing Ornament	Uncovered Ornament	Treatment Prior to 1987	New Ornament Impression
					
Added/Rearranged Ornament	Crack Fill	Altered Shape or Contour	New Damage	Lost Ornament Impression	Removed Treatment Prior to 1987

NOTE: Dashed line indicates uncertainty/need of verification



Interior South Wall  
Pannel 17  
1987















Interior South Wall  
 Panel 17  
 2011





2011 Analysis/Comparison of Site in  
 Relation to 1987 Rand Photos

LEGEND

					
Mortar Reattachment	New Mortar Application	Missing Ornament	Uncovered Ornament	Treatment Prior to 1987	New Ornament Impression
					
Added/Rearranged Ornament	Crack Fill	Altered Shape or Contour	New Damage	Lost Ornament Impression	Removed Treatment Prior to 1987

NOTE: Dashed line indicates uncertainty/need of verification

Interior South Wall  
Panel 18  
1987















Interior South Wall  
 Panel 18  
 2011



2011 Analysis/Comparison of Site in  
 Relation to 1987 Rand Photos

LEGEND

					
Mortar Reattachment	New Mortar Application	Missing Ornament	Uncovered Ornament	Treatment Prior to 1987	New Ornament Impression
					
Added/Rearranged Ornament	Crack Fill	Altered Shape or Contour	New Damage	Lost Ornament Impression	Removed Treatment Prior to 1987

NOTE: Dashed line indicates uncertainty/need of verification

Interior South Wall  
Panel 19  
1987















Interior South Wall  
 Panel 19  
 2011



2011 Analysis/Comparison of Site in  
 Relation to 1987 Rand Photos

LEGEND


					
Mortar Reattachment	New Mortar Application	Missing Ornament	Uncovered Ornament	Treatment Prior to 1987	New Ornament Impression
					
Added/Rearranged Ornament	Crack Fill	Altered Shape or Contour	New Damage	Lost Ornament Impression	Removed Treatment Prior to 1987

NOTE: Dashed line indicates uncertainty/need of verification

Interior South Wall  
Panel 20  
1987















Interior South Wall  
 Panel 20  
 2011



2011 Analysis/Comparison of Site in  
 Relation to 1987 Rand Photos


LEGEND

					
Mortar Reattachment	New Mortar Application	Missing Ornament	Uncovered Ornament	Treatment Prior to 1987	New Ornament Impression
					
Added/Rearranged Ornament	Crack Fill	Altered Shape or Contour	New Damage	Lost Ornament Impression	Removed Treatment Prior to 1987

NOTE: Dashed line indicates uncertainty/need of verification



Interior South Wall  
Panel 21  
1987















Interior South Wall  
 Panel 21  
 2011




2011 Analysis/Comparison of Site in  
 Relation to 1987 Rand Photos

LEGEND

					
Mortar Reattachment	New Mortar Application	Missing Ornament	Uncovered Ornament	Treatment Prior to 1987	New Ornament Impression
					
Added/Rearranged Ornament	Crack Fill	Altered Shape or Contour	New Damage	Lost Ornament Impression	Removed Treatment Prior to 1987

NOTE: Dashed line indicates uncertainty/need of verification

Interior South Wall  
Panel 22  
1987















Interior South Wall  
 Panel 22  
 2011




2011 Analysis/Comparison of Site in  
 Relation to 1987 Rand Photos

LEGEND

					
Mortar Reattachment	New Mortar Application	Missing Ornament	Uncovered Ornament	Treatment Prior to 1987	New Ornament Impression
					
Added/Rearranged Ornament	Crack Fill	Altered Shape or Contour	New Damage	Lost Ornament Impression	Removed Treatment Prior to 1987

NOTE: Dashed line indicates uncertainty/need of verification

Interior South Wall  
Panel 23  
1987















Interior South Wall  
 Panel 23  
 2011




2011 Analysis/Comparison of Site in  
 Relation to 1987 Rand Photos

LEGEND


					
Mortar Reattachment	New Mortar Application	Missing Ornament	Uncovered Ornament	Treatment Prior to 1987	New Ornament Impression
					
Added/Rearranged Ornament	Crack Fill	Altered Shape or Contour	New Damage	Lost Ornament Impression	Removed Treatment Prior to 1987

NOTE: Dashed line indicates uncertainty/need of verification

Interior South Wall  
Front Gate  
1987















Interior South Wall  
 Front Gate  
 2011



2011 Analysis/Comparison of Site in  
 Relation to 1987 Rand Photos

LEGEND

					
Mortar Reattachment	New Mortar Application	Missing Ornament	Uncovered Ornament	Treatment Prior to 1987	New Ornament Impression
					
Added/Rearranged Ornament	Crack Fill	Altered Shape or Contour	New Damage	Lost Ornament Impression	Removed Treatment Prior to 1987


NOTE: Dashed line indicates uncertainty/need of verification



Interior South Wall  
Panel 24  
1987















Interior South Wall  
 Panel 24  
 2011



2011 Analysis/Comparison of Site in  
 Relation to 1987 Rand Photos

LEGEND

					
Mortar Reattachment	New Mortar Application	Missing Ornament	Uncovered Ornament	Treatment Prior to 1987	New Ornament Impression
					
Added/Rearranged Ornament	Crack Fill	Altered Shape or Contour	New Damage	Lost Ornament Impression	Removed Treatment Prior to 1987

NOTE: Dashed line indicates uncertainty/need of verification

Interior South Wall  
Panel 25  
1987















Interior South Wall  
 Panel 25  
 2011




2011 Analysis/Comparison of Site in  
 Relation to 1987 Rand Photos

LEGEND

					
Mortar Reattachment	New Mortar Application	Missing Ornament	Uncovered Ornament	Treatment Prior to 1987	New Ornament Impression
					
Added/Rearranged Ornament	Crack Fill	Altered Shape or Contour	New Damage	Lost Ornament Impression	Removed Treatment Prior to 1987

NOTE: Dashed line indicates uncertainty/need of verification

Interior South Wall  
Garage Gate  
1987















Interior South Wall  
Garage Gate  
2011



2011 Analysis/Comparison of Site in  
Relation to 1987 Rand Photos

LEGEND

					
Mortar Reattachment	New Mortar Application	Missing Ornament	Uncovered Ornament	Treatment Prior to 1987	New Ornament Impression
					
Added/Rearranged Ornament	Crack Fill	Altered Shape or Contour	New Damage	Lost Ornament Impression	Removed Treatment Prior to 1987

NOTE: Dashed line indicates uncertainty/need of verification