



Comparison of 1987 and 2011
Photographs of Watts Towers Sculptures

Center Tower (CTO)

December 14, 2012

Center Tower
Panel 1
1987



Center Tower
Panel 1
2012



| 2012 Analysis/Comparison of Site in Relation to 1987 Rand Photos | | | | | | | | | | | |
|--|--|--|--|--|--|--|--|--|--|--|--|
| LEGEND | | | | | | | | | | | |
| | | | | | | | | | | | |
| Color Change | Mortar Reattachment | New Mortar Application | Missing Ornament | Uncovered Ornament | Treatment Prior to 1987 | TRANSPARENT | | | | | |
| | | | | | | | | | | | |
| Added/Rearranged Ornament | Crack Fill | | Altered Shape or Contour | | New Damage | TRANSPARENT | | | | | |
| | | | | | | | | | | | |
| | | | | | | TRANSPARENT | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |

NOTE: Dashed line indicates uncertainty/need of verification

Center Tower
Panel 2
1987



Center Tower
Panel 2
2012




| 2012 Analysis/Comparison of Site in Relation to 1987 Rand Photos | | | | | | | |
|---|---|---|---|---|---|---|---|
| LEGEND | | | | | | | |
| | | | | | | | |
| Color Change | Mortar Reattachment | New Mortar Application | Missing Ornament | Uncovered Ornament | Treatment Prior to 1987 | New Ornament Impression | TRANSPARENT |
| | | | | | | | |
| Added/Rearranged Ornament | Crack Fill | Altered Shape or Contour | New Damage | Lost Ornament Impression | TRANSPARENT | TRANSPARENT | TRANSPARENT |

NOTE: Dashed line indicates uncertainty/need of verification

Center Tower
Panel 3
1987



Center Tower
Panel 3
2012



Color Change

2012 Analysis/Comparison of Site in
Relation to 1987 Rand Photos

LEGEND



Mortar Reattachment



New Mortar Application



Missing Ornament



Uncovered Ornament



Treatment Prior to 1987



TRANSPARENT
New Ornament
Impression



Added/Rearranged Ornament



Crack Fill




Altered Shape or Contour



New Damage



TRANSPARENT
Lost Ornament
Impression



TRANSPARENT
Removed Treatment
Prior to 1987

NOTE: Dashed line indicates uncertainty/need of verification

Center Tower
Panel 4
1987



Center Tower
Panel 4
2012




| 2012 Analysis/Comparison of Site in Relation to 1987 Rand Photos | | | | | | | | | | | |
|---|---------------------------|---|------------------------|--|--------------------------|--|--------------------|--|-------------------------|---|-------------|
| LEGEND | | | | | | | | | | | |
| | Color Change | | | | | | | | | | |
| | Mortar Reattachment | | New Mortar Application | | Missing Ornament | | Uncovered Ornament | | Treatment Prior to 1987 | | TRANSPARENT |
| | Added/Rearranged Ornament | | Crack Fill | | Altered Shape or Contour | | New Damage | | TRANSPARENT | | TRANSPARENT |
| | | | | | | | | | | | |
| | | | | | | | | | | | |
| | | | | | | | | | | | |

NOTE: Dashed line indicates uncertainty/need of verification

Center Tower
Panel 5
1987



Center Tower
Panel 5
2012



2012 Analysis/Comparison of Site in
Relation to 1987 Rand Photos

LEGEND

| | |
|--|---------------------------------|
| | |
| | Mortar Reattachment |
| | New Mortar Application |
| | Missing Ornament |
| | Uncovered Ornament |
| | Treatment Prior to 1987 |
| | TRANSPARENT |
| | New Ornament Impression |
| | Added/Rearranged Ornament |
| | Crack Fill |
| | Altered Shape or Contour |
| | New Damage |
| | TRANSPARENT |
| | Lost Ornament Impression |
| | Removed Treatment Prior to 1987 |

NOTE: Dashed line indicates uncertainty/need of verification

Center Tower
Panel 6
1987



Center Tower


Panel 6

2012



2012 Analysis/Comparison of Site in Relation to 1987 Rand Photos

LEGEND

| | | | | | |
|---|---|---|--|---|---|
|  |  |  |  |  |  |
| Mortar Reattachment | New Mortar Application | Missing Ornament | Uncovered Ornament | Treatment Prior to 1987 | New Ornament Impression |
|  |  |  |  |  |  |
| Added/Rearranged Ornament | Crack Fill | Altered Shape or Contour | New Damage | Lost Ornament Impression | Removed Treatment Prior to 1987 |

NOTE: Dashed line indicates uncertainty/need of verification

Center Tower
Panel 7
1987



Center Tower
Panel 7
2012



2012 Analysis/Comparison of Site in
Relation to 1987 Rand Photos

LEGEND

| | |
|--|---------------------------------|
| | |
| | Mortar Reattachment |
| | New Mortar Application |
| | Missing Ornament |
| | Uncovered Ornament |
| | Treatment Prior to 1987 |
| | New Ornament Impression |
| | Added/Rearranged Ornament |
| | Crack Fill |
| | Altered Shape or Contour |
| | New Damage |
| | Lost Ornament Impression |
| | Removed Treatment Prior to 1987 |

NOTE: Dashed line indicates uncertainty/need of verification

Center Tower
Panel 8
1987



Center Tower
Panel 8
2012



Color Change

2012 Analysis/Comparison of Site in
Relation to 1987 Rand Photos

LEGEND



Mortar Reattachment



New Mortar Application



Missing Ornament



Uncovered Ornament



Treatment Prior to 1987



TRANSPARENT
New Ornament
Impression



Added/Rearranged Ornament



Crack Fill




Altered Shape or Contour



New Damage



TRANSPARENT
Lost Ornament
Impression




TRANSPARENT
Removed Treatment
Prior to 1987

NOTE: Dashed line indicates uncertainty/need of verification

Center Tower
Columns 1e, 1m, and 2e
1987



Center Tower
Columns 1e, 1m and 2e
2012



Color Change

2012 Analysis/Comparison of Site in
Relation to 1987 Rand Photos

LEGEND



Mortar Reattachment



New Mortar Application



Missing Ornament



Uncovered Ornament



Treatment Prior to 1987




New Ornament
Impression



Added/Rearranged Ornament



Crack Fill




Altered Shape or Contour



New Damage





Lost Ornament
Impression




Removed Treatment
Prior to 1987

NOTE: Dashed line indicates uncertainty/need of verification

Center Tower
Columns 2e, 2i, 2m and 3e
1987



Center Tower
Columns 2e, 2i, 2m and 3e
2012



Color Change

2012 Analysis/Comparison of Site in
Relation to 1987 Rand Photos

LEGEND



Mortar Reattachment



New Mortar Application



Missing Ornament



Uncovered Ornament



Treatment Prior to 1987




TRANSPARENT
New Ornament
Impression



Added/Rearranged Ornament



Crack Fill



Altered Shape or Contour



New Damage






TRANSPARENT
Lost Ornament
Impression




TRANSPARENT
Removed Treatment
Prior to 1987

NOTE: Dashed line indicates uncertainty/need of verification

Center Tower
Columns 3e, 3i, 3m, 4i and 4e
1987



Center Tower
Columns 3e, 3i, 3m, 4i and 4e
2012



Color Change

2012 Analysis/Comparison of Site in
Relation to 1987 Rand Photos

LEGEND



Mortar Reattachment



New Mortar Application




Missing Ornament



Uncovered Ornament



Treatment Prior to 1987




New Ornament
Impression



Added/Rearranged Ornament



Crack Fill



Altered Shape or Contour



New Damage




Lost Ornament
Impression



Removed Treatment
Prior to 1987

NOTE: Dashed line indicates uncertainty/need of verification

Center Tower
Columns 4e, 4m, 5i, and 5e
1987



Center Tower
Columns 4e, 4m, 5i, and 5e
2012



Color Change

2012 Analysis/Comparison of Site in
Relation to 1987 Rand Photos

LEGEND



Mortar Reattachment



New Mortar Application




Missing Ornament



Uncovered Ornament



Treatment Prior to 1987



TRANSPARENT
New Ornament
Impression



Added/Rearranged Ornament



Crack Fill




Altered Shape or Contour



New Damage




TRANSPARENT
Lost Ornament
Impression



TRANSPARENT
Removed Treatment
Prior to 1987

NOTE: Dashed line indicates uncertainty/need of verification

Center Tower
Columns 5e, 5m, 6i, and 6e
1987



Center Tower
Columns 5e, 5m, 6i, and 6e
2012



Color Change

2012 Analysis/Comparison of Site in
Relation to 1987 Rand Photos

LEGEND



Mortar Reattachment



New Mortar Application




Missing Ornament



Uncovered Ornament



Treatment Prior to 1987



TRANSPARENT
New Ornament
Impression



Added/Rearranged Ornament



Crack Fill




Altered Shape or Contour



New Damage





TRANSPARENT
Lost Ornament
Impression




TRANSPARENT
Removed Treatment
Prior to 1987

NOTE: Dashed line indicates uncertainty/need of verification

Center Tower
Columns 6e, 6i, 6m, 7i and 7e
1987



Center Tower
Columns 6e, 6i, 6m, 7i and 7e
2012



Color Change

2012 Analysis/Comparison of Site in
Relation to 1987 Rand Photos

LEGEND



Mortar Reattachment



New Mortar Application



Missing Ornament



Uncovered Ornament



Treatment Prior to 1987



TRANSPARENT
New Ornament
Impression



Added/Rearranged Ornament



Crack Fill



Altered Shape or Contour



New Damage




TRANSPARENT
Lost Ornament
Impression




TRANSPARENT
Removed Treatment
Prior to 1987

NOTE: Dashed line indicates uncertainty/need of verification

Center Tower
Columns 7e, 7m, 8i and 8e
1987



Center Tower
Columns 7e, 7m, 8i and 8e
2012



Color Change

2012 Analysis/Comparison of Site in
Relation to 1987 Rand Photos

LEGEND



Mortar Reattachment



New Mortar Application



Missing Ornament



Uncovered Ornament



Treatment Prior to 1987



TRANSPARENT
New Ornament
Impression



Added/Rearranged Ornament



Crack Fill



Altered Shape or Contour



New Damage




TRANSPARENT
Lost Ornament
Impression



TRANSPARENT
Removed Treatment
Prior to 1987

NOTE: Dashed line indicates uncertainty/need of verification

Center Tower
Columns 1e, 8i and 8e
1987



Center Tower
Columns 1e, 8i and 8e
2012



Color Change

2012 Analysis/Comparison of Site in
Relation to 1987 Rand Photos

LEGEND



Mortar Reattachment



New Mortar Application



Missing Ornament



Uncovered Ornament



Treatment Prior to 1987



TRANSPARENT
New Ornament
Impression



Added/Rearranged Ornament



Crack Fill



Altered Shape or Contour



New Damage



TRANSPARENT
Lost Ornament
Impression



TRANSPARENT
Removed Treatment
Prior to 1987

NOTE: Dashed line indicates uncertainty/need of verification