


Comparison of 1987 and 2011
Photographs of Watts Towers Sculptures

East Tower (ETO)

October 29, 2012

East Tower
Panel 1
1987
















East Tower
Panel 1
2012




2012 Analysis/Comparison of Site in
Relation to 1987 Rand Photos

LEGEND

						
Color Change						New Ornament Impression
						
Mortar Reattachment	New Mortar Application	Missing Ornament	Uncovered Ornament	Treatment Prior to 1987		
						
Added/Rearranged Ornament	Crack Fill	Altered Shape or Contour	New Damage	Lost Ornament Impression	Removed Treatment Prior to 1987	

NOTE: Dashed line indicates uncertainty/need of verification

East Tower
Panel 2
1987
















East Tower
Panel 2
2012



2012 Analysis/Comparison of Site in
Relation to 1987 Rand Photos

LEGEND


						
Color Change						
						
Mortar Reattachment	New Mortar Application	Missing Ornament	Uncovered Ornament	Treatment Prior to 1987	TRANSPARENT	New Ornament Impression
						
Added/Rearranged Ornament	Crack Fill	Altered Shape or Contour	New Damage	Lost Ornament Impression	TRANSPARENT	Removed Treatment Prior to 1987

NOTE: Dashed line indicates uncertainty/need of verification

East Tower
Panel 3
1987
















East Tower
Panel 3
2012



2012 Analysis/Comparison of Site in
Relation to 1987 Rand Photos

LEGEND

						
Color Change						
						
Mortar Reattachment	New Mortar Application	Missing Ornament	Uncovered Ornament	Treatment Prior to 1987	TRANSPARENT New Ornament Impression	
						
Added/Rearranged Ornament	Crack Fill	Altered Shape or Contour	New Damage	TRANSPARENT Lost Ornament Impression	TRANSPARENT Removed Treatment Prior to 1987	

NOTE: Dashed line indicates uncertainty/need of verification

East Tower
Panel 4
1987
















East Tower
 Panel 4
 2012




2012 Analysis/Comparison of Site in
 Relation to 1987 Rand Photos

LEGEND


						
Color Change						
						
Mortar Reattachment	New Mortar Application	Missing Ornament	Uncovered Ornament	Treatment Prior to 1987	TRANSPARENT	New Ornament Impression
						
Added/Rearranged Ornament	Crack Fill	Altered Shape or Contour	New Damage	Lost Ornament Impression	TRANSPARENT	Removed Treatment Prior to 1987

NOTE: Dashed line indicates uncertainty/need of verification

East Tower
Panel 5
1987
















East Tower
Panel 5
2012




2012 Analysis/Comparison of Site in
Relation to 1987 Rand Photos

LEGEND

						
Color Change						
						
Mortar Reattachment	New Mortar Application	Missing Ornament	Uncovered Ornament	Treatment Prior to 1987	TRANSPARENT	New Ornament Impression
						
Added/Rearranged Ornament	Crack Fill	Altered Shape or Contour	New Damage	Lost Ornament Impression	TRANSPARENT	Removed Treatment Prior to 1987

NOTE: Dashed line indicates uncertainty/need of verification

East Tower
Panel 6
1987
















East Tower
 Panel 6
 2012




2012 Analysis/Comparison of Site in
 Relation to 1987 Rand Photos

LEGEND

						
Color Change						
						
Mortar Reattachment	New Mortar Application	Missing Ornament	Uncovered Ornament	Treatment Prior to 1987	TRANSPARENT	New Ornament Impression
						
Added/Rearranged Ornament	Crack Fill	Altered Shape or Contour	New Damage	Lost Ornament Impression	TRANSPARENT	Removed Treatment Prior to 1987

NOTE: Dashed line indicates uncertainty/need of verification

East Tower
Panel 7
1987
















East Tower
Panel 7
2012



2012 Analysis/Comparison of Site in
Relation to 1987 Rand Photos

LEGEND

						
Color Change						
						
Mortar Reattachment	New Mortar Application	Missing Ornament	Uncovered Ornament	Treatment Prior to 1987	TRANSPARENT	New Ornament Impression
						
Added/Rearranged Ornament	Crack Fill	Altered Shape or Contour	New Damage	Lost Ornament Impression	TRANSPARENT	Removed Treatment Prior to 1987

NOTE: Dashed line indicates uncertainty/need of verification

East Tower
Panel 8
1987
















East Tower
 Panel 8
 2012



2012 Analysis/Comparison of Site in
 Relation to 1987 Rand Photos

LEGEND

						
Color Change						
						
Mortar Reattachment	New Mortar Application	Missing Ornament	Uncovered Ornament	Treatment Prior to 1987	TRANSPARENT	New Ornament Impression
						
Added/Rearranged Ornament	Crack Fill	Altered Shape or Contour	New Damage	Lost Ornament Impression	TRANSPARENT	Removed Treatment Prior to 1987

NOTE: Dashed line indicates uncertainty/need of verification

East Tower
Panel 9
1987
















East Tower
Panel 9
2012



**2012 Analysis/Comparison of Site in
Relation to 1987 Rand Photos**

LEGEND

 Color Change					
 Mortar Reattachment	 New Mortar Application	 Missing Ornament	 Uncovered Ornament	 Treatment Prior to 1987	 New Ornament Impression
 Added/Rearranged Ornament	 Crack Fill	 Altered Shape or Contour	 New Damage	 Lost Ornament Impression	 Removed Treatment Prior to 1987

NOTE: Dashed line indicates uncertainty/need of verification

East Tower
Panel 10
1987
















East Tower
 Panel 10
 2012



2012 Analysis/Comparison of Site in
 Relation to 1987 Rand Photos

LEGEND


						
Color Change						
						
Mortar Reattachment	New Mortar Application	Missing Ornament	Uncovered Ornament	Treatment Prior to 1987	TRANSPARENT	New Ornament Impression
						
Added/Rearranged Ornament	Crack Fill	Altered Shape or Contour	New Damage	Lost Ornament Impression	TRANSPARENT	Removed Treatment Prior to 1987

NOTE: Dashed line indicates uncertainty/need of verification

East Tower
Columns 1 and 2
1987
















East Tower
Columns 1 and 2
2012



2012 Analysis/Comparison of Site in
Relation to 1987 Rand Photos

LEGEND


						
Color Change						
						TRANSPARENT
Mortar Reattachment	New Mortar Application	Missing Ornament	Uncovered Ornament	Treatment Prior to 1987		New Ornament Impression
						TRANSPARENT
Added/Rearranged Ornament	Crack Fill	Altered Shape or Contour	New Damage	Lost Ornament Impression		Removed Treatment Prior to 1987

NOTE: Dashed line indicates uncertainty/need of verification

East Tower
Columns 2 and 3
1987
















East Tower
Columns 2 and 3
2012




2012 Analysis/Comparison of Site in
Relation to 1987 Rand Photos

LEGEND

						
Color Change						
						
Mortar Reattachment	New Mortar Application	Missing Ornament	Uncovered Ornament	Treatment Prior to 1987	TRANSPARENT	New Ornament Impression
						
Added/Rearranged Ornament	Crack Fill	Altered Shape or Contour	New Damage	Lost Ornament Impression	TRANSPARENT	Removed Treatment Prior to 1987

NOTE: Dashed line indicates uncertainty/need of verification

East Tower
Columns 4 and 5
1987
















East Tower
Columns 4 and 5
2012



2012 Analysis/Comparison of Site in
Relation to 1987 Rand Photos

LEGEND

						
Color Change						
						
Mortar Reattachment	New Mortar Application	Missing Ornament	Uncovered Ornament	Treatment Prior to 1987	TRANSPARENT	New Ornament Impression
						
Added/Rearranged Ornament	Crack Fill	Altered Shape or Contour	New Damage	Lost Ornament Impression	TRANSPARENT	Removed Treatment Prior to 1987

NOTE: Dashed line indicates uncertainty/need of verification

East Tower
Columns 5 and 6
1987
















East Tower
Columns 5 and 6
2012



2012 Analysis/Comparison of Site in
Relation to 1987 Rand Photos

LEGEND

						
Color Change						
						TRANSPARENT
Mortar Reattachment	New Mortar Application	Missing Ornament	Uncovered Ornament	Treatment Prior to 1987		New Ornament Impression
						TRANSPARENT
Added/Rearranged Ornament	Crack Fill	Altered Shape or Contour	New Damage	Lost Ornament Impression		Removed Treatment Prior to 1987

NOTE: Dashed line indicates uncertainty/need of verification

East Tower
Column 6
1987
















East Tower
Column 6
2012



2012 Analysis/Comparison of Site in
Relation to 1987 Rand Photos

LEGEND

						
Color Change						
						
Mortar Reattachment	New Mortar Application	Missing Ornament	Uncovered Ornament	Treatment Prior to 1987	TRANSPARENT New Ornament Impression	
						
Added/Rearranged Ornament	Crack Fill	Altered Shape or Contour	New Damage	Lost Ornament Impression	TRANSPARENT Removed Treatment Prior to 1987	

NOTE: Dashed line indicates uncertainty/need of verification

East Tower
Core (between columns 2i and 3i)
1987
















East Tower
Core (between columns 2i and 3i)
2012



2012 Analysis/Comparison of Site in
Relation to 1987 Rand Photos

LEGEND

						
Color Change						
						
Mortar Reattachment	New Mortar Application	Missing Ornament	Uncovered Ornament	Treatment Prior to 1987	TRANSPARENT	New Ornament Impression
						
Added/Rearranged Ornament	Crack Fill	Altered Shape or Contour	New Damage	Lost Ornament Impression	TRANSPARENT	Removed Treatment Prior to 1987

NOTE: Dashed line indicates uncertainty/need of verification

East Tower
Core (between columns 3e and 4i)
1987
















East Tower
 Core (between columns 3e and 4i)
 2012



2012 Analysis/Comparison of Site in
 Relation to 1987 Rand Photos

LEGEND

						
Color Change						
						
Mortar Reattachment	New Mortar Application	Missing Ornament	Uncovered Ornament	Treatment Prior to 1987	TRANSPARENT	New Ornament Impression
						
Added/Rearranged Ornament	Crack Fill	Altered Shape or Contour	New Damage	Lost Ornament Impression	TRANSPARENT	Removed Treatment Prior to 1987

NOTE: Dashed line indicates uncertainty/need of verification

East Tower
Core (between columns 4e and 4i)
1987
















East Tower
 Core (between columns 4e and 4i)
 2012



2012 Analysis/Comparison of Site in
 Relation to 1987 Rand Photos

LEGEND

						
Color Change						
						
Mortar Reattachment	New Mortar Application	Missing Ornament	Uncovered Ornament	Treatment Prior to 1987	TRANSPARENT	New Ornament Impression
						
Added/Rearranged Ornament	Crack Fill	Altered Shape or Contour	New Damage	Lost Ornament Impression	TRANSPARENT	Removed Treatment Prior to 1987

NOTE: Dashed line indicates uncertainty/need of verification

East Tower
Core (between columns 5i and 6i)
1987
















East Tower
 Core (between columns 5i and 6i)
 2012



2012 Analysis/Comparison of Site in
 Relation to 1987 Rand Photos

LEGEND

						
Color Change						
						TRANSPARENT
Mortar Reattachment	New Mortar Application	Missing Ornament	Uncovered Ornament	Treatment Prior to 1987		New Ornament Impression
						TRANSPARENT
Added/Rearranged Ornament	Crack Fill	Altered Shape or Contour	New Damage	Lost Ornament Impression		Removed Treatment Prior to 1987

NOTE: Dashed line indicates uncertainty/need of verification

East Tower
Core (between columns 5e and 6i)
1987
















East Tower
Core (between columns 5e and 6i)
2012



2012 Analysis/Comparison of Site in
Relation to 1987 Rand Photos

LEGEND

						
Color Change						
						TRANSPARENT
Mortar Reattachment	New Mortar Application	Missing Ornament	Uncovered Ornament	Treatment Prior to 1987		New Ornament Impression
						TRANSPARENT
Added/Rearranged Ornament	Crack Fill	Altered Shape or Contour	New Damage	Lost Ornament Impression		Removed Treatment Prior to 1987

NOTE: Dashed line indicates uncertainty/need of verification

East Tower
Core (between columns 6e and 6i)
1987
















East Tower
 Core (between columns 6e and 6i)
 2012



2012 Analysis/Comparison of Site in
 Relation to 1987 Rand Photos

LEGEND

						
Color Change						
						
Mortar Reattachment	New Mortar Application	Missing Ornament	Uncovered Ornament	Treatment Prior to 1987	TRANSPARENT	New Ornament Impression
						
Added/Rearranged Ornament	Crack Fill	Altered Shape or Contour	New Damage	Lost Ornament Impression	TRANSPARENT	Removed Treatment Prior to 1987

NOTE: Dashed line indicates uncertainty/need of verification