

Comparison of 1987 and 2011
Photographs of Watts Towers Sculptures

West Tower (WTO)

October 29, 2012

West Tower
North Stairs
1987



West Tower
North Stairs
2012



<div> <div></div> <div>Color Change</div> </div>					
<div> <div></div> <div>Mortar Reattachment</div> </div>					
<div> <div></div> <div>New Mortar Application</div> </div>					
<div> <div></div> <div>Missing Ornament</div> </div>					
<div> <div></div> <div>Uncovered Ornament</div> </div>					
<div> <div></div> <div>Treatment Prior to 1987</div> </div>					
<div> <div>TRANSPARENT</div> <div>New Ornament Impression</div> </div>					
<div> <div></div> <div>Added/Rearranged Ornament</div> </div>					
<div> <div></div> <div>Crack Fill</div> </div>					
<div> <div></div> <div>Altered Shape or Contour</div> </div>					
<div> <div></div> <div>New Damage</div> </div>					
<div> <div>TRANSPARENT</div> <div>Lost Ornament Impression</div> </div>					
<div> <div>TRANSPARENT</div> <div>Removed Treatment Prior to 1987</div> </div>					

NOTE: Dashed line indicates uncertainty/need of verification

West Tower
South Stairs Left
1987



West Tower
South Stairs Left
2012



2012 Analysis/Comparison of Site in
Relation to 1987 Rand Photos

LEGEND

<div data-bbox="147 1446 336 1499" style="background-color: #8B0000; width: 116px; height: 25px; margin-bottom: 5px;"></div> <div data-bbox="175 1507 306 1535">Color Change</div>					
<div data-bbox="147 1562 336 1614" style="background-color: #FF0000; width: 116px; height: 25px; margin-bottom: 5px;"></div> <div data-bbox="144 1623 339 1648">Mortar Reattachment</div>	<div data-bbox="376 1562 565 1614" style="background-color: #00FF00; width: 116px; height: 25px; margin-bottom: 5px;"></div> <div data-bbox="370 1623 586 1648">New Mortar Application</div>	<div data-bbox="605 1562 794 1614" style="background-color: #0000FF; width: 116px; height: 25px; margin-bottom: 5px;"></div> <div data-bbox="621 1623 794 1648">Missing Ornament</div>	<div data-bbox="834 1562 1023 1614" style="background-color: #FFA500; width: 116px; height: 25px; margin-bottom: 5px;"></div> <div data-bbox="834 1623 1023 1648">Uncovered Ornament</div>	<div data-bbox="1063 1562 1252 1614" style="background-color: #800080; width: 116px; height: 25px; margin-bottom: 5px;"></div> <div data-bbox="1052 1623 1263 1648">Treatment Prior to 1987</div>	<div data-bbox="1292 1562 1481 1614" style="background-color: #FFFF00; width: 116px; height: 25px; margin-bottom: 5px;"></div> <div data-bbox="1312 1575 1461 1600">TRANSPARENT</div> <div data-bbox="1321 1623 1468 1675">New Ornament Impression</div>
<div data-bbox="147 1682 336 1734" style="background-color: #FFFF00; width: 116px; height: 25px; margin-bottom: 5px;"></div> <div data-bbox="110 1743 375 1770">Added/Rearranged Ornament</div>	<div data-bbox="376 1682 565 1734" style="background-color: #FF00FF; width: 116px; height: 25px; margin-bottom: 5px;"></div> <div data-bbox="427 1743 516 1770">Crack Fill</div>	<div data-bbox="605 1682 794 1734" style="background-color: #00FFFF; width: 116px; height: 25px; margin-bottom: 5px;"></div> <div data-bbox="589 1743 821 1770">Altered Shape or Contour</div>	<div data-bbox="834 1682 1023 1734" style="background-color: #FFFFFF; width: 116px; height: 25px; margin-bottom: 5px;"></div> <div data-bbox="873 1743 992 1770">New Damage</div>	<div data-bbox="1063 1682 1252 1734" style="background-color: #00FF00; width: 116px; height: 25px; margin-bottom: 5px;"></div> <div data-bbox="1084 1696 1230 1719">TRANSPARENT</div> <div data-bbox="1092 1743 1230 1795">Lost Ornament Impression</div>	<div data-bbox="1292 1682 1481 1734" style="background-color: #800080; width: 116px; height: 25px; margin-bottom: 5px;"></div> <div data-bbox="1312 1696 1461 1719">TRANSPARENT</div> <div data-bbox="1292 1743 1481 1795">Removed Treatment Prior to 1987</div>

NOTE: Dashed line indicates uncertainty/need of verification

West Tower
South Stairs Right
1987




West Tower
South Stairs Right
2012




<div> <div></div> <div>Color Change</div> </div>					
<div> <div></div> <div>Mortar Reattachment</div> </div>					
<div> <div></div> <div>Added/Rearranged Ornament</div> </div>					
<div> <div></div> <div>Crack Fill</div> </div>					
<div> <div></div> <div>Altered Shape or Contour</div> </div>					
<div> <div></div> <div>New Damage</div> </div>					
<div> <div></div> <div>Lost Ornament Impression</div> </div>					
<div> <div></div> <div>Removed Treatment Prior to 1987</div> </div>					
<div> <div></div> <div>TRANSPARENT</div> </div>					
<div> <div></div> <div>TRANSPARENT</div> </div>					
<div> <div></div> <div>TRANSPARENT</div> </div>					

NOTE: Dashed line indicates uncertainty/need of verification

West Tower
Panels 1 and 2
1987



West Tower
Panels 1 and 2
2012



<div> <div></div> <div>Color Change</div> </div>					
<div> <div></div> <div>Mortar Reattachment</div> </div>					
<div> <div></div> <div>New Mortar Application</div> </div>					
<div> <div></div> <div>Missing Ornament</div> </div>					
<div> <div></div> <div>Uncovered Ornament</div> </div>					
<div> <div></div> <div>Treatment Prior to 1987</div> </div>					
<div> <div></div> <div>TRANSPARENT</div> <div>New Ornament Impression</div> </div>					
<div> <div></div> <div>Added/Rearranged Ornament</div> </div>					
<div> <div></div> <div>Crack Fill</div> </div>					
<div> <div></div> <div>Altered Shape or Contour</div> </div>					
<div> <div></div> <div>New Damage</div> </div>					
<div> <div></div> <div>TRANSPARENT</div> <div>Lost Ornament Impression</div> </div>					
<div> <div></div> <div>TRANSPARENT</div> <div>Removed Treatment Prior to 1987</div> </div>					

NOTE: Dashed line indicates uncertainty/need of verification

West Tower
Panels 6 and 7
1987



West Tower
Panels 6 and 7
2012




<div> <div></div> <div>Color Change</div> </div>						<div> <div>2012 Analysis/Comparison of Site in Relation to 1987 Rand Photos</div> <div>LEGEND</div> </div>					
<div> <div></div> <div>Mortar Reattachment</div> </div>	<div> <div></div> <div>New Mortar Application</div> </div>	<div> <div></div> <div>Missing Ornament</div> </div>	<div> <div></div> <div>Uncovered Ornament</div> </div>	<div> <div></div> <div>Treatment Prior to 1987</div> </div>	<div> <div>TRANSPARENT</div> <div>New Ornament Impression</div> </div>						
<div> <div></div> <div>Added/Rearranged Ornament</div> </div>	<div> <div></div> <div>Crack Fill</div> </div>	<div> <div></div> <div>Altered Shape or Contour</div> </div>	<div> <div></div> <div>New Damage</div> </div>	<div> <div>TRANSPARENT</div> <div>Lost Ornament Impression</div> </div>	<div> <div>TRANSPARENT</div> <div>Removed Treatment Prior to 1987</div> </div>						

NOTE: Dashed line indicates uncertainty/need of verification














West Tower
Panels 8 and 9
1987



West Tower
Panels 8 and 9
2012



2012 Analysis/Comparison of Site in
Relation to 1987 Rand Photos
LEGEND

					
Color Change					
					
Mortar Reattachment	New Mortar Application	Missing Ornament	Uncovered Ornament	Treatment Prior to 1987	New Ornament Impression
					
Added/Rearranged Ornament	Crack Fill	Altered Shape or Contour	New Damage	Lost Ornament Impression	Removed Treatment Prior to 1987

NOTE: Dashed line indicates uncertainty/need of verification

West Tower
Panels 10 and 11
1987



West Tower
Panels 10 and 11
2012



Panel 11

Panel 10


<div> <div></div> <div>Color Change</div> </div>					
<div> <div></div> <div>Mortar Reattachment</div> </div>					
<div> <div></div> <div>New Mortar Application</div> </div>					
<div> <div></div> <div>Missing Ornament</div> </div>					
<div> <div></div> <div>Uncovered Ornament</div> </div>					
<div> <div></div> <div>Treatment Prior to 1987</div> </div>					
<div> <div></div> <div>Added/Rearranged Ornament</div> </div>					
<div> <div></div> <div>Crack Fill</div> </div>					
<div> <div></div> <div>Altered Shape or Contour</div> </div>					
<div> <div></div> <div>New Damage</div> </div>					
<div> <div></div> <div>Lost Ornament Impression</div> </div>					
<div> <div></div> <div>Removed Treatment Prior to 1987</div> </div>					

NOTE: Dashed line indicates uncertainty/need of verification

West Tower
Panels 14 and 15
1987



West Tower
Panels 14 and 15
2012



<div> <div></div> <div>Color Change</div> </div>						<div> <div>2012 Analysis/Comparison of Site in Relation to 1987 Rand Photos</div> <div>LEGEND</div> </div>					
<div> <div></div> <div>Mortar Reattachment</div> </div>	<div> <div></div> <div>New Mortar Application</div> </div>	<div> <div></div> <div>Missing Ornament</div> </div>	<div> <div></div> <div>Uncovered Ornament</div> </div>	<div> <div></div> <div>Treatment Prior to 1987</div> </div>	<div> <div>TRANSPARENT</div> <div>New Ornament Impression</div> </div>						
<div> <div></div> <div>Added/Rearranged Ornament</div> </div>	<div> <div></div> <div>Crack Fill</div> </div>	<div> <div></div> <div>Altered Shape or Contour</div> </div>	<div> <div></div> <div>New Damage</div> </div>	<div> <div>TRANSPARENT</div> <div>Lost Ornament Impression</div> </div>	<div> <div>TRANSPARENT</div> <div>Removed Treatment Prior to 1987</div> </div>						

NOTE: Dashed line indicates uncertainty/need of verification

West Tower
Panel 16
1987
















West Tower
Panel 16
2012



2012 Analysis/Comparison of Site in
Relation to 1987 Rand Photos

LEGEND

					
Color Change					
					
Mortar Reattachment	New Mortar Application	Missing Ornament	Uncovered Ornament	Treatment Prior to 1987	New Ornament Impression
					
Added/Rearranged Ornament	Crack Fill	Altered Shape or Contour	New Damage	Lost Ornament Impression	Removed Treatment Prior to 1987

NOTE: Dashed line indicates uncertainty/need of verification

West Tower
Columns 1 and 16
1987



West Tower
Columns 1 and 16
2012



<div> <div></div> <div>Color Change</div> </div>						<div> <div>2012 Analysis/Comparison of Site in Relation to 1987 Rand Photos</div> <div>LEGEND</div> </div>					
<div> <div></div> <div>Mortar Reattachment</div> </div>	<div> <div></div> <div>New Mortar Application</div> </div>	<div> <div></div> <div>Missing Ornament</div> </div>	<div> <div></div> <div>Uncovered Ornament</div> </div>	<div> <div></div> <div>Treatment Prior to 1987</div> </div>	<div> <div>TRANSPARENT</div> <div>New Ornament Impression</div> </div>						
<div> <div></div> <div>Added/Rearranged Ornament</div> </div>	<div> <div></div> <div>Crack Fill</div> </div>	<div> <div></div> <div>Altered Shape or Contour</div> </div>	<div> <div></div> <div>New Damage</div> </div>	<div> <div>TRANSPARENT</div> <div>Lost Ornament Impression</div> </div>	<div> <div>TRANSPARENT</div> <div>Removed Treatment Prior to 1987</div> </div>						

NOTE: Dashed line indicates uncertainty/need of verification

West Tower
Columns 2 and 3
1987
















West Tower
Columns 2 and 3
2012




2012 Analysis/Comparison of Site in
Relation to 1987 Rand Photos

LEGEND

					
Color Change					
					
Mortar Reattachment	New Mortar Application	Missing Ornament	Uncovered Ornament	Treatment Prior to 1987	New Ornament Impression
					
Added/Rearranged Ornament	Crack Fill	Altered Shape or Contour	New Damage	Lost Ornament Impression	Removed Treatment Prior to 1987

NOTE: Dashed line indicates uncertainty/need of verification

West Tower
Columns 4 and 5
1987



LEGEND

NOTE: Dashed line indicates uncertainty/need of verification

West Tower
Columns 5 and 6
1987



LEGEND

NOTE: Dashed line indicates uncertainty/need of verification

West Tower
Columns 7 and 8
1987
















West Tower
Columns 7 and 8
2012



2012 Analysis/Comparison of Site in
Relation to 1987 Rand Photos

LEGEND

					
Color Change					
					
Mortar Reattachment	New Mortar Application	Missing Ornament	Uncovered Ornament	Treatment Prior to 1987	New Ornament Impression
					
Added/Rearranged Ornament	Crack Fill	Altered Shape or Contour	New Damage	Lost Ornament Impression	Removed Treatment Prior to 1987

NOTE: Dashed line indicates uncertainty/need of verification

West Tower
Columns 8 and 9
1987



West Tower
Columns 8 and 9
2012



<div> <div></div> <div>Color Change</div> </div>					
<div> <div></div> <div>Mortar Reattachment</div> </div>					
<div> <div></div> <div>New Mortar Application</div> </div>					
<div> <div></div> <div>Missing Ornament</div> </div>					
<div> <div></div> <div>Uncovered Ornament</div> </div>					
<div> <div></div> <div>Treatment Prior to 1987</div> </div>					
<div> <div>TRANSPARENT</div> <div>New Ornament Impression</div> </div>					
<div> <div></div> <div>Added/Rearranged Ornament</div> </div>					
<div> <div></div> <div>Crack Fill</div> </div>					
<div> <div></div> <div>Altered Shape or Contour</div> </div>					
<div> <div></div> <div>New Damage</div> </div>					
<div> <div>TRANSPARENT</div> <div>Lost Ornament Impression</div> </div>					
<div> <div>TRANSPARENT</div> <div>Removed Treatment Prior to 1987</div> </div>					

NOTE: Dashed line indicates uncertainty/need of verification

West Tower
Columns 10 and 11
1987



West Tower
Columns 10 and 11
2012



2012 Analysis/Comparison of Site in
Relation to 1987 Rand Photos

LEGEND


<div data-bbox="144 1556 334 1610" style="display: inline-block; width: 117px; height: 26px; background-color: #8B0000; border: 1px solid black;"></div>					
Color Change					
<div data-bbox="144 1671 334 1726" style="display: inline-block; width: 117px; height: 26px; background-color: #FF0000; border: 1px solid black;"></div>	<div data-bbox="375 1671 565 1726" style="display: inline-block; width: 117px; height: 26px; background-color: #00FF00; border: 1px solid black;"></div>	<div data-bbox="605 1671 795 1726" style="display: inline-block; width: 117px; height: 26px; background-color: #0000FF; border: 1px solid black;"></div>	<div data-bbox="836 1671 1026 1726" style="display: inline-block; width: 117px; height: 26px; background-color: #FFA500; border: 1px solid black;"></div>	<div data-bbox="1066 1671 1256 1726" style="display: inline-block; width: 117px; height: 26px; background-color: #800080; border: 1px solid black;"></div>	<div data-bbox="1297 1671 1487 1726" style="display: inline-block; width: 117px; height: 26px; background-color: #FFFF00; border: 1px solid black; text-align: center;">TRANSPARENT</div>
Mortar Reattachment	New Mortar Application	Missing Ornament	Uncovered Ornament	Treatment Prior to 1987	New Ornament Impression
<div data-bbox="144 1791 334 1845" style="display: inline-block; width: 117px; height: 26px; background-color: #FFFF00; border: 1px solid black;"></div>	<div data-bbox="375 1791 565 1845" style="display: inline-block; width: 117px; height: 26px; background-color: #FF00FF; border: 1px solid black;"></div>	<div data-bbox="605 1791 795 1845" style="display: inline-block; width: 117px; height: 26px; background-color: #00FFFF; border: 1px solid black;"></div>	<div data-bbox="836 1791 1026 1845" style="display: inline-block; width: 117px; height: 26px; background-color: #FFFFFF; border: 1px solid black;"></div>	<div data-bbox="1066 1791 1256 1845" style="display: inline-block; width: 117px; height: 26px; background-color: #00FF00; border: 1px solid black; text-align: center;">TRANSPARENT</div>	<div data-bbox="1297 1791 1487 1845" style="display: inline-block; width: 117px; height: 26px; background-color: #800080; border: 1px solid black; text-align: center;">TRANSPARENT</div>
Added/Rearranged Ornament	Crack Fill	Altered Shape or Contour	New Damage	Lost Ornament Impression	Removed Treatment Prior to 1987

NOTE: Dashed line indicates uncertainty/need of verification

West Tower
Columns 12 and 13
1987
















West Tower
Columns 12 and 13
2012



2012 Analysis/Comparison of Site in
Relation to 1987 Rand Photos

LEGEND

					
Color Change					
					
Mortar Reattachment	New Mortar Application	Missing Ornament	Uncovered Ornament	Treatment Prior to 1987	New Ornament Impression
					
Added/Rearranged Ornament	Crack Fill	Altered Shape or Contour	New Damage	Lost Ornament Impression	Removed Treatment Prior to 1987

NOTE: Dashed line indicates uncertainty/need of verification

West Tower
Columns 14 and 15
1987
















West Tower
Columns 14 and 15
2012



2012 Analysis/Comparison of Site in
Relation to 1987 Rand Photos

LEGEND

					
Color Change					
					
Mortar Reattachment	New Mortar Application	Missing Ornament	Uncovered Ornament	Treatment Prior to 1987	New Ornament Impression
					
Added/Rearranged Ornament	Crack Fill	Altered Shape or Contour	New Damage	Lost Ornament Impression	Removed Treatment Prior to 1987

NOTE: Dashed line indicates uncertainty/need of verification